

Settlement	SHLAA Ref	Site Location	Location Type	Designated Heritage Assets										Non-Designated Heritage Assets				Site Specific Comments and Notes	
				Harm to a Conservation Area	Harm to the setting of a Conservation Area	Harm to Scheduled Monument	Harm to setting of a Scheduled Monument	Harm to a Listed Building	Harm to setting of a Listed Building	Harm to a Registered Park and Garden	Harm to the setting of a Registered Park and Garden	Harm to a Registered Battlefield site	Harm to Setting of a Registered Battlefield site	Harm to setting of buildings of Historical Significance	Harm to Surviving Ridge and Furrow	Harm to Archaeological 'Monuments'	Harm to sites with evidence of archaeological 'Events'		
Alderminster	ALD.01	North of Shipston Road (west)	LSV4																Aerial photograph of ridge and furrow
Alderminster	ALD.02	West of Sutcliffe Avenue	LSV4																Ridge and furrow region. MWA19690 surviving ridge and furrow. Aerial photograph of ridge and furrow
Alderminster	ALD.03	North of Sutcliffe Avenue	LSV4																Ridge and furrow region. MWA19690 surviving ridge and furrow. Aerial photograph of ridge and furrow
Alderminster	ALD.04	South of New Road	LSV4																MWA1197 - The site of a possible Medieval deserted settlement
Alderminster	ALD.05	East of Campden Lawns	LSV4																Aerial photograph of ridge and furrow
Alderminster	ALD.06	North of Tithe Farm (west)	LSV4																No non-designated heritage assets recorded
Alderminster	ALD.07	North of Tithe Farm (east)	LSV4																Aerial photograph of ridge and furrow
Alderminster	ALD.08	North of Shipston Road (east)	LSV4																Aerial photograph of ridge and furrow
Alderminster	ALD.09	South of Shipston Road	LSV4																MWA6435 - The remains of a Medieval shrunken village are visible as earthworks on aerial photographs. Aerial photograph of deserted settlement. Aerial photograph of quarry